

ASSEMBLY / WIRING


eventCON

1




Prepare the cable. Make sure PE cable is longer than L & N cable.

2




Thread Seals Nut, Seals Ring, Clamp Ring and Gasket onto the cable.

3




Solder wire.



Pin definition:


1:	GND	L:	Line
2:	Data -	N:	Neutral
3:	Data +	⊕	Protective earth

4




Assemble Gasket into Clamp ring:
Gasket Direction
(Flat Surface to Housing)

5




Assemble Clamp Ring to the housing.
Torque: 3 Nm

6



Put Seals Ring to the end of Clamp Ring

7



Assemble Seals Nut and Clamp Ring.
Torque: 3 Nm

Please consider to your own safety:

Only qualified electrician are allowed to wire the eventCON system or to solder plugs onto the eventCON cable.
Please contact your local dealer for further information if necessary.